

Electrical Circle-2

Annexure-I

STATUS of Existing Parks as on 17-11-12

S. NO	Name of Park (Sub Div./ Section wise)	Total nos. of Parks	Parks Lights			Tubewells			Benches in NO.	Playing equipments		Remarks
			Total NO.	Functioning	Not Functioning	Total No.	Functioning	Not Functioning		Slides	Swings	
1.	Electrical Division-4 (Hort. Div.-5)	62 Nos.	632 Nos.	513 Nos.	119 Nos.	84 Nos.	73 Nos.	11 Nos.	-	-	-	Out of 11 nos. pumps shown not working, 8 nos. pumps not functional as the bore water is salty. However treated water is being used.
2.	Electrical Division-7 (Hort. Div.-10)	25 Nos.	29 Nos.	24 Nos.	5 Nos.	50 Nos.	36 Nos.	14 Nos.	-	-	-	12 nos. borewells to be redeveloped for which tenders are being called
3.	Electrical Division-8 (Hort. Div.-2&10)	96 Nos.	1608 Nos.	1212 Nos.	396 Nos.	194 Nos.	163 Nos.	31 Nos.	-	-	-	17 nos. borewells to be re-developed for which tenders are being called
Total of Electrical Circle-2		183 Nos.	2269 Nos.	1749 Nos.	520 Nos.	328 Nos.	272 Nos.	56 Nos.				a) <u>Pumps</u> 8 Nos. not required, 29 Nos. to be re-developed and balance 19 Nos. under repair. b) <u>Regarding lights</u> At most places fittings are missing/damaged.

[Signature]
S. E. E. T. - 4

Annexure - 2

SE(E)-2

NAME OF IC — Sh. Mahesh Sharma.

S.No.	Location of Park	TUBE WELLS		Not Functioning	Remarks
		Total Nos	Functioning		
1.	Distt. Park Multan Nagar	3 Nos	3 No	—	
2.	Sanjay Van Pitampura	2 Nos	1 No	1 No	Under repair
3.	Millan Appth. Pitampura	1 No	1 No	—	
4.	Brij Vihar Pitampura	2 Nos	2 No	—	
5.	Tarun Vihar Pitampura	1 No	1 No	—	
6.	Club Wala Park Pitampura	1 No	1 No	—	
7.	Zonal Green Saraswati Vihar	3 No	2 No	1 No	(1 Bore damaged)
8.	Sainik Vihar Pitampura	4 No	3 No	1 No	(1 Bore damaged)
9.	Anand Vihar Pitampura	2 No	2 No	—	
10.	Harsh Vihar Pitampura	4 No	3 No	1 No	Cable damaged
11.	Deepali Chowk Pitampura	1 No	1 No	—	
12.	Lok Vihar Pitampura	4 No	3 No	1 No	(1 Bore damaged)
13.	Sandesh Encl. Pitampura Pitampura	5 No	4 No	1 No	(1 Bore damaged)

	Super Nua	Working	Not functioning	Remarks
14.	Kohat Encl. Pitampura	1 No	1 No	—
15.	Rajdhani Encl. Pitampura	1 No	1 No	—
16.	Rajdhani Encl. Pitampura	—	—	—
17.	Road No. 42 Pitampura	1 No	1 No	—
18.	Sanjay Park Shakarpur	1 No	1 No	—
19.	Division of Fice Pitampura	1 No	1 No	—
20.	M.D. Park Lawrence Road	3 No	2 No	1 No (Bore damaged)
21.	Nepal Wala Park Lawrence Road	3 No	3 Nos.	—
22.	Mazdoor Ala Park Lawrence Road	2 No	2 No	—
23.	C-1 Pahari Park Lawrence Road	1 No	1 No	—
24.	Rose Garden Lawrence Road	1 No	1 No	—
25.	Charkhi Wala Park Shastri Nagar	2 No	2 No	—
26.	Gulabi Bagh	3 No	3 No	—
27.	Darbar Khan (N) Shastri Nagar	2 No	2 No	—
28.	Picnic Ashok Vihar	1 No	1 No	—
29.	Zonal Green Ashok Vihar	2 No	2 No	—

30.	Ashoka Garden Ashok Vihar	10 No	9 No	Not functioning	Remarks
31.	Green Belt Ashok Vihar Phase I	5 No	3 Nos	2 Nos	(Motor fallen)
32.	Chandi Wala Bagh Ashok Vihar	2 No	1 No	1 No	(Bore damaged, pump house down)
33.	Nursery Ashok Vihar -II	2 No	1 No	1 No	(Bore damaged)
34.	Bode Wala Park Ashok Vihar -II	1 No	—	1 No	(Bore choked)
35.	Lekhram Park Ashok Vihar -II	2 Nos	2 Nos	—	:
36.	Rly Line App. B. Bldg Ashok Vihar -II	2 No	1 No	1 No	:
37.	Satyawati College Ashok Vihar -II	1 No	—	1 No	:
38.	Janak Wala Park Ashok Vihar -II	2 Nos	2 Nos	—	
39.	Subhash Place Pitampura	2 Nos	2 Nos	—	
40.	Pitampura Village Subhash Place Pitampura	1 No	1 No	—	
41.	Shakarpur Garden Subhash Place Pitampura	1 No	—	1 No	(Bore choked)
42.	Tikri Kala Subhash Place Pitampura	1 No	1 No	—	
43.	Green Belt Shastri Nagar	1 No	1 No	—	

	Park Shastri Nagar	1 No	1 No	—	—
45.	56 Bigha Park Shastri Nagar	7 Nos	5 No	2 Nos	(Cable damaged)
46.	Taken Wali Bagichi Shastri Nagar	1 No	1 No	—	—
47.	Singhore Kala Gulabi Bagh	2 Nos	2 Nos	—	—
48.	Lilawati Park Shastri Nagar	1 No	—	1 No	(Under Repair)
49.	Shastri Nagar Rly. Line	1 No	1 No	—	—
50.	Lalsingh park Shastri Nagar	1 No	1 No	—	—
51.	Regional Park (Ashok Vihar) (Khimman Singh Park)	1 No	1 No	—	—
52.	Khojewala Park (Ashok Vihar) (Khimman Singh Park)	1 No	1 No	—	—
53.	N.H.P. Ashok Vihar -III	1 No	1 No	—	—
54.	Metro Pillar 285 Lawrence Road.	1 No	1 No	—	—
55.	Green Belt Lokvihar and Chanderlok	2 Nos	1 No	1 No	(Bore checked)
	TOTAL	114 Nos.	94 Nos.	20 Nos.	

Drilled
 02-4/2008

DELHI DEVELOPMENT AUTHORITY

DETAILS OF PUMPS SETS HOT DIVN. 20

TUBE WELLS

NAME OF JE :- SH. S.C. JAIN.

S.No	LOCATION	TOTAL PUMPS	WORKING	NOT WORKING	REMARKS
SHALIMAR BAGH					
1	Distt. Park Ram Bagh (Subj) (Mono block)	1 no.	1 no.	---	
2	Distt park Block AP	2 nos.	1 no.	1 no.	No Water in bore well.
3	NHP Block BC- BL Ramilla Wala Parks	2 no.	1	1 No.	No Water in bore well.
4	Community centre BK Block	1 no.	1 no.	---	
5	NHP Block BQ - BM	1 no.	1 no.	---	
6	Motewy wala Bagh BR Block	2 nos.	2 nos.		
7	Ram Swaroop Thakurdass wala bagh	2 nos.	2 nos.	---	
8	Malhotra wala bagh AG Block	1 no.	1 no.	--	

		<u>TOTAL PUMPS</u>	<u>WORKING</u>	<u>NOT WORKING</u>	<u>REMARKS</u>
9.	NHP Block A	1no.	1no.	--	
10	Kaley Raghubir wala bagh	1no.	1no.	---	
11	Bateshwar wala bagh	2nos.	2nos.	---	
12	Sad wala bagh	1no.	1no.	--	
13	Karnail wala bagh	2nos.	1no.	1no.	Bore well choked.
14	Takiya wala	1no.	1no.	--	
15	Motey wala	2nos.	2nos.	---	
16	Aihru wala	1no.	1no.	---	
17	Mariyam wala	1no.	1no.	--	
18	Nali wala	1no.	1no.	--	
19	Jolly No.2	1no.	--	1no.	Pipe missing
20	Jolly no.1	1no.	1no.	--	
21	Baniya wala	2nos.	1no.	1no.	CABLE fault.

Sl. No.	Particulars	Q1/18	Q2/18	Q3/18	Q4/18
22	Distt. Park				
23	Nanak wala bagh opp. Outer Ring road -Haidar pur	1no.	1no.	1no.	1no.
24	G/Belt B/W Shalamar village & Rly. Line	1no.	1no.	1no.	1no.
25	Tikona park Bhalswa colony	1no.	1no.	1no.	1no.
26	656 MIG flat Jahangir puri	1no.	1no.	1no.	1no.
PITAPURA					
1	Distt. Park Lake area, Sub:- monoblock Weda Pump.	5 nos.	5 nos.	2 Nos.	1 No.
2	NHP Block HU	1no.	1no.	1no.	1no.
3	Distt. Park Lala ram wala Bagh	2nos.	2nos.	2nos.	2nos.

	QU Block Double tanki)					
5	Community centre KP Block	1no.	1no.	--		
6	NHP Block ND	1no.	1no.	--		
7	Distt. Park RP Block <u>Submersible</u> 1no. (Kejurena wala) monoblock 1no.	1no.	1no.	--		
8	Distt. Park SP block (Ramila wala)	1no.	1no.	--		
9	Aziz box wala bagh (Beri wala bagh)	1no.	1no.	---		
10	Distt. Park SP-TP Block (Near Haryana central)	2nos.	1no.	1no.		Bore well checked.
11	Block TP	1no.	1no.	--		
12	Northan Ridge -phase -I	7nos.	6nos.	1no.		Bore well checked.

Sl. No.	IVOLUTIDII RIDGE- P.N.II&III (Sub.)	8 nos. 3 Nos.	6 nos. 3 Nos.	2 Nos.	Umdur report
14	16 No Lake Road Nursery (Sub.) Northan Ridge (monobloc)	1 no.	1 no.	--	
15	Ajeet Garh, Malka Ganj, Old Subzi MANDI, New Subji Mandi.	5 nos.	5 nos.	--	
		1 no.		1 no.	Cable fault
	G. Total	80 Nos.	69 Nos.	11 Nos.	

Total pumps
(Hort. Division 24/10)

194 163 31

Sanjay
AE-4/60-8

DELHI DEVELOPMENT AUTHORITY

DETAILS OF LIGHT POINTS UNDER HORT. DIVN.2 AS ON 17.11.12

NAME OF JE — SH. MAHESH SHARMA

S.No	LOCATION	TOTAL FITTING	WORKING	NOT WORKING	REMARKS
1	Distt. Park Multan Nagar	20 Nos	16 Nos	4 Nos	Cable damaged
2	Sanjay Park Pitampura	12	8 Nos	4 Nos	— do — on one pole
3	Millan Appnt. Pitampura	24 Nos	22 Nos	2 Nos	Fitting damaged
4	Brij Vihar Pitampura	54 Nos	48 Nos	6 Nos	
5	Tarun Vihar Pitampura	36 Nos	26 Nos	10 Nos	
6	Club wala park pitampura	29 Nos	24 Nos	5 Nos	
7	Zonal Green Saraswati Vihar	49 Nos	37 Nos	12 Nos	
8	Anand Vihar Pitampura	67 Nos	48 Nos	14 Nos	Globe missing wire from pole missing
9	Harsh Vihar Pitampura 9 mtr - 4 Nos	76 Nos	32 Nos	44 Nos	Cable damaged, 4 Nos. Fitting missing
10	Deepali Chowk Pitampura	19 Nos	19 Nos	—	
11	Lok Vihar Pitampura	44 Nos	38 Nos	6 Nos	
12	Sandesh Vihar Pitampura	130	71	59	

13	Kohat Encl. Pitampura	12 Nos.	12 Nos.	NIL	
14	Rajdhani Encl. Pitampura	30 Nos.	28 Nos.	2 Nos.	Cable damaged.
15	Road no. 42 Pitampura	24 Nos.	20 Nos.	4 Nos.	Fitting damaged
16	Sanjay Park Shakarpur	8 Nos.	6 Nos.	2 Nos.	
17	Division office Pitampura	12 Nos.	12 Nos.	—	
18	M.D. park Lawrence Road	38 Nos.	29 Nos.	9 Nos.	Cable damaged, fitting stolen
19	Nepal wala park Lawrence Road	43 Nos.	37 Nos.	6 Nos.	Fitting broken
20	Mazdoor wala park Lawrence road	42 Nos.	29 Nos.	13 Nos.	Cable damaged
21	C-1 Pahari Park Lawrence road	—	—	—	—
22	Rose Garden Lawrence road	35 Nos.	22 Nos.	13 Nos.	Cable damaged, fitting broken
23	Charkhi wala park Shastri	28 Nos.	6 Nos.	22 Nos.	fitting damaged and stolen Cable damaged

	Nagar				
24	Gulabi Bagh	14 Nos	---	14 Nos.	All the fittings damaged by monkeys.
25	Darbar Khan (N) Shastri nagar	24 Nos	10 Nos	14 No	Fitting damaged & missing by monkeys
26	Picnic hut, Ashok Vihar	62 Nos	43 Nos	19 Nos	Cable damaged. Fitting damaged.
27	Zonal Green Ashok Vihar	20 No.	12 Nos	8 Nos	Cable damaged.
28	Ashok Garden Ashok Vihar	52 Nos.	40 Nos.	12 Nos.	Cable damaged.
29	Green Belt Ashok Vihar	32 Nos	30 Nos	2 No	-
30	Chandi Wala bagh Ashok Vihar	22 Nos	20 Nos	2 Nos	(Fitting damaged)
31	Nursary Ashok Vihar - II	12 Nos	6 Nos	6 Nos.	
32	Bode wala partk Ashok Vihar-II	12 Nos	6 No	6 No	(4 Nos fittings Stolen)
33	Lekhram Park Ashok Vihar -	46 Nos.	41 Nos	5 Nos	Fitting damaged and st.
Total.		974 Nos.	684 Nos	290 Nos.	Spent

DETAILS OF LIGHT POINTS UNDER HORT. DIVN.10 AS ON 17.11.12

NAME OF JE — SH. S.C. JAIN.

PARKS LIGHTS

S.No	LOCATION	TOTAL FITTING	WORKING	NOT WORKING	REMARKS
	Shalimar Bagh				
1	Distt. Park Ram bagh	40 nos.	38 nos.	2 nos.	
2	AA block	24 nos.	22 nos.	2 nos.	
3	DA block	4 nos.	3 nos.	1 no.	
4	Karnail Wala bagh	30 nos.	26 nos.	4 nos.	
5	Thakur Dass wala Bagh	72 nos.	65 nos.	7 nos.	
6	Motey Wala bagh	69 nos.	50 nos.	19 nos.	Fitting stolen
7	BM/BQ Block	41 nos.	33 nos.	8 nos.	
8	Sheesh Mahal	23 nos.	18 nos.	5 nos.	
9	AP Block	14 nos.	12 nos.	2 nos.	
	PITAMPURA				
1	Distt park Pitampura	84 nos.	80 nos.	4 nos.	

		51 nos.	40 nos.	11 nos.	
3	SU MU Block (DOUBLE TURNKEY)	5 nos.		5 nos.	Cable fault
4	HU Block	6 nos.	6 nos.		
5	N.D. Block	12 nos.	10 nos.	2 nos.	
6	R.P. Block	11 nos.	10 nos.	1 no.	
7	SP TP Block	33 nos.	30 nos.	3 nos.	
8	TP Block	4 nos.		4 nos.	Cable fault
9	Northern Ridge Ph. 1, II, III & Subzi Mandi	111 nos.	85 nos.	26 nos.	Fitting missing
G. Total		634 nos.	526 nos.	106 nos.	

Total light points.

(Hort. Division 2 + 10).

1608 1212 396.

Santhya
22-9/2008

Annexure-2Details of Expenditure

1.	Total upto date Expenditure Incurred w.e.f. 1-04-2012	=	12,04,072 = 00
2.	Total number of parks	=	96
3.	Total number of complaints received	=	60 73
4.	Total number of complaints attended :		
a)	Regarding park lights	=	21
b)	Replacement of pumps	=	NIL
c)	Repair of pumps	=	52
d)	Miscellaneous	=	—
5.	Expenditure incurred per park	=	12,540 = 00 84
6.	Expenditure incurred per complaints attended	=	

Verified
DB-4/60-8

Status of Existing Parks as on 17.11.2012 in Division No. 7 (Narela)

S.No.	Name of Park (Sub-Division/ Section wise)	Park Ligts			Tubewells			Benches (in)	Playing		Remarks
		Total No.	Functioning	Not Functioning	Total No.	Functioning	Not Functioning		Slides	Swings	
1	M/O MP green area old orchard, Sec. A-10, (Near Kurani Vill.)	0	4 Nos.	----	1	1	----	----	----	----	----
2	M/O Park RSP, LIG, MIG, Pkt. 2,4,6 Sec. A-10, Narela				3	----	----	3 Nos.	----	----	3 Nos bore under redevelopment tender under process for redevelopment bore
3	M/O Park i/c seed bed old orchard, Narela					1	4 Nos.	----	----	----	Civil wing constructed the road work pole to be dismantled
4	M/O Sawran Jayanti Vihar Tikri Khurd, Narela	4 Nos.	----	----	1	1	----	----	----	----	----
5	M/O Park Play area Sec. B-2, Narela				2	2	----	----	----	----	----
6	M/O Old orchard Subhash Wala Bagh, Narela				1	1	----	----	----	----	----
7	M/O Green Belt along 80 Mtr. Road, G.T. Road to office complex, Narela				3	3	----	----	----	----	----
8	M/O Central verge along 80 Mtr. Road, Narela				2	2	----	----	----	----	----
9	M/O Old orchard Pardha Wala Bagh, Narela				1	1	----	----	----	----	----
10	M/O Park Play area Sec. A-6, Narela	4 Nos.	4 Nos.	----	2	2	----	----	----	----	----
11	M/O Park 608 EWS Pkt. -5, 13, Sec. A-6, Narela				2	1	----	----	----	----	Motor under repair
12	M/O Distt. Park (Smirtivan) Sec. A-7, Narela		8 Nos.	1 Nos.	4	3	1	----	----	----	1 Nos bore under development tender under process for redevelopment of bore
13	M/O Green Belt Sec. A-6, Narela	9 Nos.	----	----							do
14	M/O Green Belt Sec. A-7, Narela		----	----	1	----	1	----	----	----	do
15	M/O Park Play area Sec. A-5, Narela	8 Nos.	8 Nos.	----	2	2	----	----	----	----	----
16	M/O NHP Sec. A-5, Narela		----	----	1	1	----	----	----	----	----
17	M/O 672 incremental houses 144 SFS Sec. A-5, Narela		----	----	2	2	----	----	----	----	----
18	M/O 660 Janta EWS Houses, Gr.III, Sc. A-5, Narela		----	----	1	----	1	----	----	----	Motor under repair
19	M/O Park, R/S Scheme Tikona Park, Sec. A-9, Narela		----	----	1	----	1	----	----	----	1 Nos bore under deveopment tender under process for redevelopment of bore
20	M/O Park 84 LIG, 64 MIG, Pkt. 1, 184 LIG, 64 MIG, Pkt.-III, 96 LIG, 120 MIG, Pkt-IV, Sec. A-9, Narela		----	----	2	1	1	----	----	----	do
21	M/O Park Play area Sec. B-4, Narela		----	----	2	2	2	----	----	----	----
22	M/O Park, 672, LIG, Pkt. 1,6,9, Sec. B-4, Narela		----	----	2	2	2	----	----	----	----

23	M/O Land shifting IFC, Narela	----	----	1	----	1	----	1	----	1	1 Nos bore under development tender under process for redevelopment of bore
24	M/O Old orchard Chhanga Wala Bagh, Narela	----	----	1	1	1	1	1	1	1	1 Nos bore under development tender under process for redevelopment of bore
25	M/O Green Belt, Sec. B-4, Narela	----	----	2	1	1	1	1	1	1	1 Nos bore under development tender under process for redevelopment of bore
26	Parks of sector B-2	----	----	8	6	6	2	2	2	2	1 Nos bore under development tender under process for redevelopment of bore
Total		29	24	5	50	36	14	14	14	14	



A.E. (E) II



J.E. (E)

DETAILS OF EXPENDITURE

- | | | |
|----|---|---------|
| 1. | Total upto date expenditure incurred w.e.f. 1.4.2012 N.D.P.L. 40 Lacks + repair 42000.00 Total 4.42 Lacks | |
| 2. | Total Number of Parks | 25 Nos. |
| 3. | Total Number of complaints received | 43 Nos. |
| 4. | Total Number of complaints attended | |
| a) | Regarding Parks lights | 10 Nos. |
| b) | Replacement of pumps | -- |
| c) | Repair of pumps | -- |
| d) | Miscellaneous | 33 Nos. |
| 5. | Expenditure incurred per park | 1700.00 |
| 6. | Expenditure incurred per complaints attended | -- |


AE(E)
JE(E)